


\*\*\*\* Scan this "reset" code first. \*\*\*\*



Response: beep,boop,beep

### GoAntiquing! Configuration sheet for "COM Port" mode Honeywell/Metrologic Barcode Scanners 1690, 3780, 9590

1. Enter Program Mode




999999

Response: beep,beep,beep

Scan codes in numbered order, but start with the special "reset" code at top of page!


6. Reserved (164.1)



116411

Response: beep


2. Clear USB Setting



816470

Response: beep


7. Reserved (164.2)



116412

Response: beep


3. Recall Defaults



999998

Response: beep


8. Enable Comm Timeout



118412

Response: beep


4. Programmable Prefix 1



80351240

Response: beep


9. Beep After Transmit



118403

Response: beep


5. Reserved (164.0)



116410

Response: beep

10. Exit Program Mode



999999

Response: beep,beep,beep