

Zebra DS8108: Programming Barcodes for DS8108

Configuration name in Utility : Zebra DS8108
Last Modified : 09-Jun-26
Windows Filename : Zebra 8108 Imaging Scanner Setup - HIDKB.scncfg
Plug-in Name : DS8108-STANDARD DL MODELS-033
Report Type : Only parameters changed from defaults shown



Zebra DS8108: Programming Barcodes for DS8108

Configuration name in Utility : Zebra DS8108
Last Modified : 09-Jun-26
Windows Filename : Zebra 8108 Imaging Scanner Setup - HIDKB.scncfg
Plug-in Name : DS8108-STANDARD DL MODELS-033
Report Type : Only parameters changed from defaults shown



Set Factory Defaults

Imaging Settings

Imaging Parameters

| | |
|--------------------------------|------|
| Image Brightness (TargetWhite) | 240 |
| Image Enhancement | High |

JPEG Image Optimization

| | |
|--------------------|----|
| JPEG Quality Value | 85 |
|--------------------|----|

Snapshot Mode

| | |
|-----------------------|------------|
| Snapshot Mode Timeout | No Timeout |
|-----------------------|------------|

Signature Capture

| | |
|--------------------------------|----|
| Signature Capture JPEG Quality | 85 |
|--------------------------------|----|

Image Cropping

| | |
|----------------------|-----|
| Bottom Pixel Address | 479 |
| Right Pixel Address | 639 |

Video

| | |
|------------------------------|----------------|
| Video View Finder | Enable |
| Video View Finder Image Size | 120 |
| Video JPEG Quality | 85 |
| Video Resolution | 1/3 Resolution |

Intelligent Document Capture

| | |
|--------------------|--------|
| IDC Operating Mode | Linked |
|--------------------|--------|

Zebra DS8108: Programming Barcodes for DS8108

Configuration name in Utility : Zebra DS8108
Last Modified : 09-Jun-26
Windows Filename : Zebra 8108 Imaging Scanner Setup - HIDKB.scncfg
Plug-in Name : DS8108-STANDARD DL MODELS-033
Report Type : Only parameters changed from defaults shown



| | |
|------------------|-------------------------------|
| IDC X Coordinate | 0 |
| IDC Y Coordinate | 0 |
| IDC Width | 640 |
| IDC Height | 480 |
| IDC JPEG Quality | 85 |
| IDC Border Type | Advanced Edge Detection (AED) |
| IDC Delay Time | 6 |

Modify Data- Advanced Data Formatting

Prefix: |

1

1

2

4

Suffix 1 Enter

7

0

1

3

Suffix 2 Enter

7

Zebra DS8108: Programming Barcodes for DS8108

Configuration name in Utility : Zebra DS8108
Last Modified : 09-Jun-26
Windows Filename : Zebra 8108 Imaging Scanner Setup - HIDKB.scncfg
Plug-in Name : DS8108-STANDARD DL MODELS-033
Report Type : Only parameters changed from defaults shown



0

1

3

Scan Data Transmission Format <Prefix><Data><Suffix 1>

General Parameter Settings

System

Decode Session Timeout 5

Beeper

Beeper Volume Low

Beeper Tone Low

OCR

OCR-A Enable

Configuration File Zebra DS8108

Notes:

Zebra 8108 in FreeForm mode using SSI and 115200 baud

Firmware:

CAACZS00-010-R01