

# Zebra DS8208: Programming Barcodes for DS8208

Configuration name in Utility : Zebra DS8208  
Last Modified : 17-Jun-26  
Windows Filename : Zebra 8208 Imaging Scanner Setup - SNAPI default to HIDKB.scncf...  
Plug-in Name : DS8208-STANDARD SR MODELS-002  
Report Type : Only parameters changed from defaults shown

---



# Zebra DS8208: Programming Barcodes for DS8208

Configuration name in Utility : Zebra DS8208  
Last Modified : 17-Jun-26  
Windows Filename : Zebra 8208 Imaging Scanner Setup - SNAPI default to HIDKB.scncf...  
Plug-in Name : DS8208-STANDARD SR MODELS-002  
Report Type : Only parameters changed from defaults shown



---

Set Factory Defaults

## Imaging Settings

---

### Imaging Parameters

Analog Gain	Analog Gain x 1
Image Brightness (TargetWhite)	120
Image Size (Number of Pixels)	1/2 Resolution
Image Enhancement	High

### JPEG Image Optimization

JPEG Size Value	240
JPEG Quality Value	85

### Snapshot Mode

Gain Exposure Priority	Low Gain Priority
Snapshot Mode Timeout	No Timeout
Silence Operational Mode Changes	Enable

### Image Cropping

Bottom Pixel Address	479
Right Pixel Address	639

### Video

Video View Finder	Enable
Video View Finder Image Size	120

# Zebra DS8208: Programming Barcodes for DS8208

Configuration name in Utility : Zebra DS8208  
Last Modified : 17-Jun-26  
Windows Filename : Zebra 8208 Imaging Scanner Setup - SNAPi default to HIDKB.scncf...  
Plug-in Name : DS8208-STANDARD SR MODELS-002  
Report Type : Only parameters changed from defaults shown



---

Video JPEG Quality	50
Video Resolution	1/3 Resolution

## Intelligent Document Capture

IDC Operating Mode	Linked
IDC X Coordinate	0
IDC Y Coordinate	0
IDC Width	640
IDC Height	480
IDC JPEG Quality	85
IDC Find Box Outline	Enable
IDC Captured Image Brighten	Disable
IDC Border Type	Advanced Edge Detection (AED)
IDC Delay Time	6

## Modify Data- Advanced Data Formatting

---

Prefix: |  
1  
1  
2  
4  
Suffix 1 Enter

# Zebra DS8208: Programming Barcodes for DS8208

Configuration name in Utility : Zebra DS8208  
Last Modified : 17-Jun-26  
Windows Filename : Zebra 8208 Imaging Scanner Setup - SNAPi default to HIDKB.scncf...  
Plug-in Name : DS8208-STANDARD SR MODELS-002  
Report Type : Only parameters changed from defaults shown



---

7  
0  
1  
3  
Suffix 2 Enter  
7  
0  
1  
3  
Scan Data Transmission Format <Prefix><Data><Suffix 1>

## General Parameter Settings

---

### System

Hand-Held Trigger Mode	Level
Hands-Free Mode	Disable
Decode Session Timeout	5
Motion Tolerance	More Motion Tolerance
Illumination Brightness	Medium

### Beeper

Beeper Volume	Low
Scan Tone	Low

# Zebra DS8208: Programming Barcodes for DS8208

Configuration name in Utility : Zebra DS8208  
Last Modified : 17-Jun-26  
Windows Filename : Zebra 8208 Imaging Scanner Setup - SNAPI default to HIDKB.scncf...  
Plug-in Name : DS8208-STANDARD SR MODELS-002  
Report Type : Only parameters changed from defaults shown



---

Beeper Duration	Short
Pager Motor After Good Decode	Disable
Configuration File	Zebra DS8208

## Firmware:

CAAGLS00-002-R00